

# Safety Information Message

Reference: SIM2206

Issued: 28 April 2022

## Drive DeVilbiss Hybrid Power Mattress - over inflation of cell

### Summary

IRIC has received several incident reports this month involving the Drive the DeVilbiss hybrid power mattress in which there has been an over inflation of a cell. Investigations are ongoing and it is too early to determine the cause.

Further information is needed to enable a full assessment of this issue and we therefore request that you **check your local adverse event management system for similar incidents and report them to IRIC.**

Information on reporting incidents to IRIC can be found here: [report an incident](#)

### Equipment details

Drive DeVilbiss- hybrid power mattress. Product code HYB/POWER.

### Enquiries

Enquiries and adverse incident reports should be addressed to:

**Incident Reporting & Investigation Centre (IRIC)**

NHS National Services Scotland

Tel: 0131 275 7575 Email: [nss.irc@nhs.scot](mailto:nss.irc@nhs.scot)

**IRIC remit:** general information about adverse incidents, safety alerts and IRIC's role can be found in [CEL 43 \(2009\)](#), *Safety of Health, Social Care, Estates and Facilities Equipment: NHS Board and Local Authority Responsibilities*, issued 30 October 2009.

**Report an incident:** Information on [how to report an adverse incident](#)

NHS National Services Scotland is the common name for the Common Services Agency for the Scottish Health Service <https://www.nss.nhs.scot/>

© Crown Copyright 2022