

Safety Information Message

Reference: SIM2207

Issued: 08 June 2022

Review Date: 08 June 2023

Product Safety Report for a Wall Lamp (Batch LB002): risk of electric shock

Summary

The UK Government's Office for Product Safety & Standards (OPSS) has produced a Product Safety Report for a Wall Lamp that does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 and presents a risk of electric shock. Destruction of the product is recommended.

Action

Refer to the OPSS Product Safety Report on the Wall Lamp [here](#) and, if applicable, follow the required action.

Equipment details

Mains powered bulkhead lamp, fitted with tails connection to the mains supplied in brown cardboard packaging. Batch number: LB002.



See Annex for additional identifying information.

Background

OPSS help manage consumer product safety incidents and provide information on products that present a serious risk to health and safety.

This OPSS Product Safety Report identifies the wall lamp as, *“presenting a serious risk of electric shock as there is possible access to live parts through the non-compliant E27 bulb holder, and the item was not adequately earthed. There was no secondary security such as a split washer or star-washer fitted to the earth terminals to prevent from accidental loosening. There was also no information with regards to the rated voltage, frequency, and current shown on the item, as*

required by the regulations. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.”

Destruction of the product is recommended

Suggested onward distribution

Health & Safety
Property Repairs

Safety Representatives
Property Services

Supplies / Procurement
Risk Management

Enquiries

Enquiries and adverse incident reports should be addressed to:

Incident Reporting & Investigation Centre (IRIC)

NHS National Services Scotland

Tel: 0131 275 7575 Email: nss.irc@nhs.scot

Accessibility: Please contact us using the above details if you are blind or have a sight impairment and would like to request this alert in a more suitable format.

IRIC remit: general information about adverse incidents, safety alerts and IRIC’s role can be found in [CEL 43 \(2009\)](#), *Safety of Health, Social Care, Estates and Facilities Equipment: NHS Board and Local Authority Responsibilities*, issued 30 October 2009.

Report an incident: Information on [how to report an adverse incident](#)


NHS National Services Scotland is the common name for the Common Services Agency for the Scottish Health Service <https://www.nss.nhs.scot/>

© Crown Copyright 2022

Annex



Office for Product
Safety & Standards

Wall Lamp	
Aspect	Details
Images	
Alert Number	2202-0283
Product Type	Lighting equipment – Wall Lamp
Product Identifiers	Batch number: LB002 Other: M010000000001738217, FANGCFGGBBB, RVG536-211123-0005-247, PO2111040134
Product Description	Mains powered bulkhead lamp, fitted with tails connection to the mains supplied in brown cardboard packaging
Country of Origin	China
Counterfeit	No
Risk Level	Serious
Risk Type	Electric shock
Risk Description	The product presents a serious risk of electric shock as there is possible access to live parts through the non-compliant E27 bulb holder, and the item was not adequately earthed. There was no secondary security such as a split washer or star-washer fitted to the earth terminals to prevent from accidental loosening. There was also no information with regards to the rated voltage, frequency, and current shown on the item. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
Corrective Measures	Destruction of the product
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <https://www.gov.uk/guidance/product-recalls-and-alerts>